

HAZARDOUS SUBSTANCES RISK ASSESSMENT

Designer Contracts Ltd

Unit 8, Church View, Coney Green, Chesterfield, S45 9HA

CPL - Bostik Screedmaster Hytec A370 Rapid	Date of Assessment : 09/12/2022	Reference : CPL - Bostik Screedmaster Hytec A370 Rapid
Risk Assessor : Laura Cross	Risk Assessor :	
Other People Involved in Making This Assessment : Antony Maidens		

R or H Descriptors:	S or P Descriptors:
Additional Information	
Workspace Exposure Limit (WEL) No WEL stated on Safety Data Sheet	

Primary route(s) of entry : Absorption, Ingestion, Inhalation	
This is a Group Substance.	The quantity used per batch or work period is: Medium (1-1000kg or 1-1000L)
The Substance is a Liquid of Low volatility	
is the control measure appropriate to control the health risks from the use of this substance. Health Surveillance is not required.	

Existing Control Measures
1. First aid measures, General advice Show this safety data sheet to the doctor in attendance. If medical advice is needed, have product container or label at hand
2. Inhalation IF exposed or concerned: Get medical advice/attention. Remove to fresh air. Eye contact Rinse thoroughly with plenty of water for at least 15 minutes, lifting lower and upper eyelids. Consult a doctor.
3. Skin contact In the case of skin irritation or allergic reactions see a doctor. Wash skin with soap and water. Ingestion Clean mouth with water. Do NOT induce vomiting. Drink 1 or 2 glasses of water. Never give anything by mouth to an unconscious pe
4. Suitable Extinguishing Media Use extinguishing measures that are appropriate to local circumstances and the surrounding environment.
5. Methods for containment Prevent further leakage or spillage if safe to do so. Methods for cleaning up Take up mechanically, placing in appropriate
6. General hygiene considerations Handle in accordance with good industrial hygiene and safety practice
7. Storage Conditions Keep container tightly closed in a dry and well-ventilated place.
8. Eye/face protection Wear safety glasses with side shields (or goggles)
9. Hand protection Wear protective gloves. Gloves must conform to standard EN 374. Ensure that the breakthrough time of the glove material is not exceeded.
10. Skin and body protection Wear suitable protective clothing. Material, acid-resistant. Respiratory protection No protective equipment is needed under normal use conditions. If exposure limits are exceeded or irritation is experienced, ventilation and evacuation may be required.

11. Waste codes should be assigned by the user based on the application for which the product was used. This mixture is classified as not hazardous according to regulation (EC) 1272/2008 Always return empty packaging to region and dispose of in Drum B

Documents Associated with this Risk Assessment : Bostik Screedmaster Hytec A370 Rapid DPM.pdf(Safety Data Sheet)

Review Date : 09/12/2023