

## HAZARDOUS SUBSTANCES RISK ASSESSMENT

### Designer Contracts Ltd

Unit 8, Church View, Coney Green, Chesterfield, S45 9HA

<b>CPL - Bostik Screedmaster C500 Ultimate Part A</b>	Date of Assessment : 04/12/2023	Reference : CPL - Bostik Screedmaster C500 Ultimate Part A
Risk Assessor : Laura Cross	Risk Assessor :	
Other People Involved in Making This Assessment : Antony Maidens		



<b>R or H Descriptors:</b>	<b>S or P Descriptors:</b>
H317 May cause an allergic skin reaction	P101 If medical advice is needed, have product container or label at hand P102 Keep out of reach of children P261 Avoid breathing dust/fume/gas/mist/vapours/spray P280 Wear protective gloves/protective clothing/eye protection/face protection P302+352 IF ON SKIN; Wash with soap and water P501 Dispose of contents/container to ...xxxxx
<b>Additional Information</b>	
P501 Dispose of contents/ container in accordance with national regulations.	
<b>Workspace Exposure Limit (WEL)</b>	
No WEL stated on Safety Data Sheet	

<b>Primary route(s) of entry :</b> Absorption, Ingestion, Inhalation	
<b>This is a Group C Substance.</b>	<b>The quantity used per batch or work period is: Medium (1-1000kg or 1-1000L)</b>
<b>The Substance is a Liquid of Low volatility</b>	
<b>Engineering Controls is the control measure appropriate to control the health risks from the use of this substance. Health Surveillance is not required.</b>	

<b>Existing Control Measures</b>
1. First aid measures inhalation Remove to fresh air. IF exposed or concerned: Get medical advice/attention
2. Eye contact Rinse thoroughly with plenty of water for at least 15 minutes, lifting lower and upper eyelids.
3. Skin contact Wash with soap and water. May cause an allergic skin reaction. In the case of skin irritation or allergic reactions see a doctor

4. Ingestion Clean mouth with water. Do NOT induce vomiting. Drink 1 or 2 glasses of water. Never give anything by mouth to an unconscious person
5. Suitable Extinguishing Media Use extinguishing measures that are appropriate to local circumstances and the surrounding environment.
6. Personal precautions Avoid contact with skin, eyes or clothing. Ensure adequate ventilation. Use personal protective equipment as required. Evacuate personnel to safe areas. Keep people away from and upwind of spill/leak
7. Methods for containment Prevent further leakage or spillage if safe to do so. Methods for cleaning up Take up mechanically, placing in appropriate containers for disposal. Prevention of secondary hazards Clean contaminated objects and areas thoroughly observing environmental regulations.
8. Advice on safe handling Handle in accordance with good industrial hygiene and safety practice. Avoid contact with skin, eyes or clothing. Wear protective gloves. Gloves must conform to standard EN 374
9. Ensure adequate ventilation. In case of insufficient ventilation, wear suitable respiratory equipment. Do not eat, drink or smoke when using this product. Take off contaminated clothing and wash it before reuse.
10. Waste codes should be assigned by the user based on the application for which the product was used all empty packaging to be returned to region and disposed of in Drum B

**Documents Associated with this Risk Assessment :** Bostik Screedmaster SL C500 Ultimate Liquid Part A.pdf(Safety Data Sheet) Bostik Screedmaster SL C500 Ultimate Liquid Part A.pdf(Safety Data Sheet)

**Review Date :** 08/12/2024