

HAZARDOUS SUBSTANCES RISK ASSESSMENT

Designer Contracts Ltd

Unit 8, Church View, Coney Green, Chesterfield, S45 9HA

CPL - Bostick Screedmaster Grip A526	Date of Assessment : 09/12/2022	Reference : CPL - Bostick Screedmaster Grip A526
Risk Assessor : Laura Cross	Risk Assessor :	
Other People Involved in Making This Assessment : Antony Maidens		



R or H Descriptors:	S or P Descriptors:
H317 May cause an allergic skin reaction	P101 If medical advice is needed, have product container or label at hand P102 Keep out of reach of children P261 Avoid breathing dust/fume/gas/mist/vapours/spray P280 Wear protective gloves/protective clothing/eye protection/face protection P302+352 IF ON SKIN; Wash with soap and water P501 Dispose of contents/container to ...xxxxx
Additional Information P501 Dispose of contents/ container in accordance with national regulations.	
Workspace Exposure Limit (WEL) No WEL stated on Safety Data Sheet	

Primary route(s) of entry : Absorption, Ingestion, Inhalation	
This is a Group C Substance.	The quantity used per batch or work period is: Medium (1-1000kg or 1-1000L)
The Substance is a Liquid of Low volatility	
Engineering Controls is the control measure appropriate to control the health risks from the use of this substance. Health Surveillance is not required.	

Existing Control Measures
1. First aid measures General advice Show this safety data sheet to the doctor in attendance. Inhalation Remove to fresh air. IF exposed or concerned: Get medical advice/attention
2. Eye contact Rinse thoroughly with plenty of water for at least 15 minutes, lifting lower and upper eyelids. Consult a doctor. Skin contact Wash with soap and water. May cause an allergic skin reaction. In the case of skin irritation or allergic reactions see a doc

- | |
|--|
| 3. Ingestion Clean mouth with water. Do NOT induce vomiting. Drink 1 or 2 glasses of water. Never give anything by mouth to an unconscious per |
| 4. Suitable Extinguishing Media Use extinguishing measures that are appropriate to local circumstances and the surrounding environment. |
| 5. Personal precautions Avoid contact with skin, eyes or clothing. Ensure adequate ventilation. Use personal protective equipment as required. Evacuate personnel to safe areas. Keep people away from and upwind of spill/leak |
| 6. Methods for containment Prevent further leakage or spillage if safe to do so. Methods for cleaning up Take up mechanically, placing in appropriate containers for disposal. Prevention of secondary hazards Clean contaminated objects and areas thoroughly observing environmental regulations |
| 7. Advice on safe handling Handle in accordance with good industrial hygiene and safety practice. Avoid contact with skin, eyes or clothing. Ensure adequate ventilation. In case of insufficient |
| 8. Storage Conditions Keep containers tightly closed in a dry, cool and well-ventilated place. Store locked up. Keep out of the reach of child |
| 9. Eye/face protection Tight sealing safety goggles. Hand protection Wear protective gloves. Gloves must conform to standard EN 374. Ensure that the breakthrough time of the glove material is not exceeded. Refer to glove supplier for information on breakthrough |
| 10. Waste codes should be assigned by the user based on the application for which the product was used. All empty packaging should be returned to region and disposed of in Drum A |

Documents Associated with this Risk Assessment : Bostik Screedmaster Grip A526 Universal Primer.pdf(Safety Data Sheet)
Review Date : 09/12/2023