

HAZARDOUS SUBSTANCES RISK ASSESSMENT

Designer Contracts Ltd

Unit 8, Church View, Coney Green, Chesterfield, S45 9HA

Title Master FAST One Coat DPM Part A	Date of Assessment : 09/02/2022	Reference : CPL-Tile Master FAST One Coat DPM Part A
Risk Assessor : Laura Cross	Risk Assessor :	
Other People Involved in Making This Assessment : Adam Denton		



R or H Descriptors:	S or P Descriptors:
H315 Causes skin irritation H317 May cause an allergic skin reaction H319 Causes serious eye irritation H411 Toxic to aquatic life with long lasting effects	P102 Keep out of reach of children P261 Avoid breathing dust/fume/gas/mist/vapours/spray P264 Wash ... thoroughly after handling P273 Avoid release to the environment P280 Wear protective gloves/protective clothing/eye protection/face protection P302+352 IF ON SKIN; Wash with soap and water P305+351+338 IF IN EYES; Rinse cautiously with water for several minutes. Remove contact lenses if present and easy to do - continue rinsing P333+313 If skin irritation or a rash occurs Get medical advice/attention P501 Dispose of contents/container to ...xxxxx
Additional Information P264 Wash contaminated skin thoroughly after handling. P501 Dispose of contents/ container in accordance with national regulations.	
Workspace Exposure Limit (WEL)	

Primary route(s) of entry : Absorption, Ingestion, Inhalation	
This is a Group C Substance.	The quantity used per batch or work period is: Medium (1-1000kg or 1-1000L)
The Substance is a Liquid of Low volatility	
Engineering Controls is the control measure appropriate to control the health risks from the use of this substance. Health Surveillance is not required.	

Existing Control Measures

1. First aid measures Inhalation Remove casualty from exposure ensuring one's own safety whilst doing so. Consult a doctor. Eye contact Consult a doctor. Bathe the eye with running water for 15 minutes.
2. Skin contact Remove all contaminated clothes and footwear immediately unless stuck to skin. Wash off immediately with plenty of soap and water. Ingestion Wash out mouth with water. Consult a doctor.
3. Extinguishing media Suitable extinguishing media for the surrounding fire should be used. Use water spray to cool containers.
4. Always use in a well Ventilated area Self-contained breathing apparatus must be available in case of emergency.
5. 08 04 09* waste adhesives and sealants containing organic solvents or other dangerous substances. Transfer to a suitable container and arrange for collection by specialise disposal company
6. Environmental precautions Contain the spillage using bunding. Do not empty into drains; dispose of this material and its container in a safe way.Methods and material for containment and cleaning up Absorb with inert, absorbent material. Transfer to suitable, labelled containers for disposal
7. Precautions for safe handling Avoid direct contact with the substance. Do not handle in a confined space. Avoid the formation or spread of mists in the air. Ensure adequate ventilation of the working area
8. Individual protection measures Approved safety goggles. Wear protective clothing. Wear suitable gloves and eye/face protection. Use appropriate personal protective equipment

Documents Associated with this Risk Assessment : MSDS-FastOneCoatDPMPartA (1).pdf(Safety Data Sheet)

Review Date : 09/02/2023