

## HAZARDOUS SUBSTANCES RISK ASSESSMENT

### Designer Contracts Ltd

Unit 8, Church View, Coney Green, Chesterfield, S45 9HA

<b>CPL Xtrafloor PS Adhesive</b>	<b>Date of Assessment :</b> 27/05/2022	<b>Reference :</b> CPL - Xtrafloor PS Adhesive
<b>Risk Assessor :</b> Laura Cross	<b>Risk Assessor :</b>	
<b>Other People Involved in Making This Assessment :</b> Stacey Brereton		

<b>R or H Descriptors:</b>	<b>S or P Descriptors:</b>
<b>Additional Information</b>	
<b>Workspace Exposure Limit (WEL)</b> No WEL stated on SDS	

<b>Primary route(s) of entry :</b> Absorption, Ingestion, Inhalation	
<b>This is a Group Substance.</b>	<b>The quantity used per batch or work period is:</b> Medium (1-1000kg or 1-1000L)
<b>The Substance is a Liquid of Low volatility</b>	
<b>is the control measure appropriate to control the health risks from the use of this substance. Health Surveillance is not required.</b>	

<b>Existing Control Measures</b>
1. Always use in a well ventilated area.
2. first aid: In case of skin contact: Wash with plenty of water and soap. In case of eyes contact: In case of contact with eyes, rinse immediately with plenty of water and seek medical advice. Wash immediately with water for at least 10 minutes.
3. First Aid con.. In case of Ingestion: Do not induce vomiting get medical attention showing SDS and hazard label
4. Extinguishing media Suitable extinguishing media: Water. CO2
5. Accidental release measures: Limit leakages with earth or sand. Do not allow to enter into soil/subsoil. Do not allow to enter into surface water or drains. Retain contaminated washing water and dispose it.
6. Accidental release measures con .. In case of gas escape or of entry into waterways, soil or drains, inform the responsible authorities. Suitable material for taking up: absorbing material, organic, sand
7. Methods and material for containment and cleaning up After the product has been recovered, rinse the area and materials involved with water. Suitable material for taking up: absorbing material, organic, sand Wash with plenty of water. Retain contaminated washing water and dispose it.
8. Avoid contact with skin and eyes, inhalation of vapours and mists
9. PPE Not needed for normal use. Anyway, operate according good working practices.

10. Keep away from food, drink and feed.

11. Always wash hands after handling product.

12. Adopt good industrial practices, so that the product is not released into the environment.

13. Waste Disposal : Disposal of hardened product (EC waste code): 08 04 10 Disposal of not hardened product (EC waste code): 08 04 16 All empty packaging to be returned to region and disposed of in Drum A

**Documents Associated with this Risk Assessment** : IVC New PS Adhesive MSDS 010219.pdf(SDS) TF Xtrafloor PS Adhesive.pdf(Safet Data Sheet)

**Review Date** : 29/06/2023