

HAZARDOUS SUBSTANCES RISK ASSESSMENT

Designer Contracts Ltd

Unit 8, Church View, Coney Green, Chesterfield, S45 9HA

| | | |
|---|--|--|
| CPL Super Flow 30 Liquid | Date of Assessment : 13/12/2023 | Reference : CPL - Tilemaster Super Flow 30 Liquid |
| Risk Assessor : Laura Cross | Risk Assessor : | |
| Other People Involved in Making This Assessment : Antony Maidens | | |

| | |
|---|----------------------------|
| R or H Descriptors: | S or P Descriptors: |
| Additional Information | |
| Workspace Exposure Limit (WEL) No WEL stated on Safety Data Sheet | |

| | |
|--|--|
| Primary route(s) of entry : Absorption, Ingestion, Inhalation | |
| This is a Group Substance. | The quantity used per batch or work period is: Medium (1-1000kg or 1-1000L) |
| The Substance is a Liquid of Low volatility | |
| is the control measure appropriate to control the health risks from the use of this substance. Health Surveillance is not required. | |

| |
|--|
| Existing Control Measures |
| 1. Always use in well ventilated areas avoid contact with skin and eyes. |
| 2. First Aid Measures: Inhalation, May cause irritation to mucous membranes. Move the exposed person to fresh air. Seek medical attention if irritation or symptoms persist. |
| 3. Eye contact: May cause irritation to eyes. Rinse immediately with plenty of water for 15 minutes holding the eyelids open. Seek medical attention if irritation or symptoms persist. |
| 4. Skin Contact: May cause irritation to skin. Wash off immediately with plenty of soap and water. Remove contaminated clothing. Seek medical attention if irritation or symptoms persist. |
| 5. Ingestion: May cause irritation to mucous membranes. DO NOT INDUCE VOMITING. Seek medical attention if irritation or symptoms persist. |
| 6. Do not allow runoff water to enter sewers or drains. Stable under normal conditions. |
| 7. Do not allow product to enter drains. Prevent further spillage if safe. |
| 8. Methods and material for containment and cleaning up: Absorb with inert, absorbent material. Sweep up. Transfer to suitable, labelled containers for disposal. Clean spillage area thoroughly with plenty of water. |
| 9. Conditions for safe storage: Keep in a cool, dry, well ventilated area. Keep containers tightly closed. Store in correctly labelled containers. Protect from frost. |
| 10. Wear protective clothing, safety goggles and chemical resistant gloves. |

11. Disposal of packaging This material and its container must be disposed of in a safe way. EWC code 08 04 09 * Always return empty packaging to region and dispose of in Drum A

Documents Associated with this Risk Assessment : Tilemaster Super Flow 30 Latex SDS.pdf(Safety Data Sheet) Superflow 30 Health (SDS)

Review Date : 23/12/2024